

# **Section 8: Supplements**



# The technical content of this document is approved by EASA under approval number 10073824

#### 8.35 CAMERON CONNECT SYSTEM

#### 8.35.1 GENERAL INFORMATION

This supplement shall be inserted in the Flight Manual, in Section 8: 'Supplements' with the revisions record sheet amended accordingly.

Information contained herein supplements, or in the case of conflict, supersedes that contained in the basic Flight Manual. For Limitations, Procedures, and Performance Data not contained in this supplement, consult the basic Hot Air Balloon Flight Manual.

Issue 3 of this supplement consists of four pages.

Supplement 7.35 (two pages) to Maintenance Manual Issue 10 is required to ensure continued airworthiness.

#### 8.35.2 LIMITATIONS

No change.

#### 8.35.3 EMERGENCY PROCEDURES

No change.

#### 8.35.4 NORMAL PROCEDURES

#### 8.35.4.2.4 ENVELOPE RIGGING

#### 8.35.4.2.4 Cameron Connect System (additional)

Unpack the two halves of the envelope and align load tape No. 1 on the upper and lower sections.

Connect the two halves of load tape No. 1 together with a Maillon link and tighten using an open ended spanner (or small adjustable). Connect the next vertical tape together with a Maillon link and firmly press the Velcro together between the two connected vertical tapes. Repeat this procedure around the envelope equator until all the tapes are connected and the Velcro seal is complete.

**Note:** On both halves of the envelope, Load tape no.1 is marked on the inside of the envelope with a short length of red tape.

17 July 2020 Issue 3 Page 1



# **Section 8: Supplements**

The Maillon links should be tightened and the integrity of the seal checked before every inflation regardless of whether the envelope has been disassembled at the end of the previous flight.

Note:

The strength of the Velcro seal is dependent on how firmly the Velcro is pressed together. It is also important to ensure the Velcro is dry and free from grass and other contaminants.

The envelope is then rigged to the burner frame in the normal manner.




Fig 1: Envelope Joint (Internal view)

#### 8.35.4.3 Cold Inflation (additional)

Partially cold inflate the envelope.

Locate the envelope pulley and karabiner on the parachute operating line (Refer to Fig.2). Clip this to the rigging loop at the top of the first full height panel above the Nomex on load tape No 1. Locate the karabiner on the end of the parachute operating line and clip this to the rigging loop at the same location on load tape No. 9 (16 gore) or No.7 (24 Gore). Check that the parachute operating line is not twisted and is running free.

Page 2 Issue 3 17 July 2020



#### 8.35.4.4 TAKE-OFF

#### 8.35.4.4.1 Pre Take-Off Checks

# Pre-Take-Off Checklist (additional) Envelope

Equatorial Seam:

Check all maillon links are present, and fully closed; no threads should be visible in the screwgate of the Maillon link.

#### 8.35.4.6 LANDING

#### 8.35.4.6.3 Action after landing (additional)

To disassemble the envelope (if required) peel the Velcro apart, at each vertical load tape undo the Maillon link to disconnect the two halves of each vertical load tape. Now disconnect the parachute operating line from the bottom half by unclipping the karabiners at the fixed point and guide pulley and clipping them to the loops provided on the top half of the envelope. Pack each half of the envelope into its bag.

#### 8.35.5 WEIGHT CALCULATIONS

No change.

# 8.35.6 BALLOON AND SYSTEMS DESCRIPTION

#### 8.35.6.2.17 Connect System

The connect two-part envelope system has been designed so the each part of the divided envelope may be carried as hold luggage on commercial airliners.

It is not necessary to disassemble the envelope into its two halves after every flight, only when transport by commercial airliners is required.




Fig 2: Connect System General Arrangement

17 July 2020 Issue 3 Page 3



# Section 8: Supplements

### 8.35.7 BALLOON MAINTENANCE, HANDLING AND CARE

No change.

# 8.35.9 EQUIPMENT LIST

No change.

Page 4 Issue 3 17 July 2020