

CAMERON BALLOONS LTD / THUNDER & COLT

SERVICE BULLETIN: SB7

Subject: **Triple Burner Frame - Post Mod C252 / T176**

Title: **Inspection of Burner Frame Cross Bar Welds**

Parts affected: **Triple Burner Frame - Post Mod C252 / T176 from March 96 to October 97 - see attached listing**

Reason for Modification/ Inspection: **Isolated incident of cracking in cross bar weld adjacent to gimbal mounting block locations.**

Modification Classification: **Mandatory**

Compliance: **A) Inspection in accordance with CBL/TN/FJD/1588.
B) Modification of Burner frame within 20hrs flight time or 3 months**

Possible Consequence of Non-Compliance: **Burner Frame cross-bar failure.**

Accomplishment Instructions: **A) Inspection in accordance with CBL/TN/FJD/1588.
B) Contact Cameron Balloons Ltd.**

If in doubt please contact the factory.

**Cameron Balloons Ltd
St John's Street
Bedminster
Bristol
BS3 4NH**

**Tel +44 (0)117 9637216
Fax +44 (0)117 9661168**