

# Service Instruction




## 1. General

(a) No.:	SI05
(b) Revision / Date	A/September 2013
(b)Title:	A-530 Rigging to CQ2015 Burner Frame
(c)Description:	Information additional to HABFM i10
(d)Applicability:	EASA.BA.013, A-530
(e)Effectivity:	All C/N

**Note:** Applicability= All types and variants to which the change can be applied.  
Effectivity= Actual CN or group of CN's to which the bulletin has been/will be applied.

## 2. Accomplishment Instructions


View from basket



3. Materials NONE

4. Other Publications Affected NONE

5. Remarks Flight manual will be updated at next revision

Compiled by: <i>S.A. Cocker</i>		Notes:
Date: 24/09/2013	Name: S.A. Cocker	
<b>6. Design Organisation Approval</b>		
<b>Approval Statement</b>		
I hereby confirm that these instructions are in compliance with all the applicable airworthiness requirements. The technical content of this document is approved under the authority of DOA nr EASA.21J.140		
Signed, for and on behalf of Cameron Balloons Ltd.		
<i>S.A. Cocker</i>		
Head of Design		
Date: 24-09-2013	Name:	