

CAMERON BALLOONS LTD and THUNDER & COLT

SERVICE BULLETIN: SB9

Title: Return to Service of Titanium Propane Cylinders.

Parts affected: Titanium propane cylinders types:

CB2380, serial numbers BT0005 onwards.
CB2383, serial numbers BT0001 to BT0010, BT0012 to BT0014,
BT0016 to BT0033 onwards.

Reason Embodiment of Cameron Modification C274 Issue 2.

Classification: Recommended.

Compliance: Receipt of cylinder release to service following rework.

Note: An 'S' suffix to the part number denotes embodiment of Cameron Modification C274 Issue 2. The 'S' suffix is engraved on cylinder identification plate.

Accomplishment Instructions. Cylinder Modification carried out by Cameron Balloons. A check for the presence of the above noted Cameron-applied suffix must be made before use.

If in doubt please contact the factory.

**Cameron Balloons Ltd /Thunder and Colt
St John's Street
Bedminster
Bristol BS3 4NH**

Tel +44 (0)117 9637216, fax +44 (0)117 9661168