

Service Letter



1. General

(a) No.:	SL 10
(b) Revision / Date	0 / January 2020
(c) Title:	Revision of Service Bulletin compliance categories.
(d) Description:	Revision of the Service Bulletin compliance categories used by Cameron Balloons from Advisory, Recommended and Highly Recommended to Advisory, Recommended and Required.
(e) Applicability:	All models / types
(f) Effectivity:	All CNs

Note: Applicability= All types and variants to which the advice can be applied.
Effectivity= Actual CN or group of CN's to which the advice applies.

2. Accomplishment Instructions

Past Service Bulletins have been categorised in one of three categories; Advisory, Recommended and Highly Recommended. Future Service Bulletins and revisions of existing bulletins will be categorised as follows:

Advisory: Issued for advice only.

Recommended: It is recommended that the actions described in the service bulletin are carried out by the operator.

Required: The actions described in the service bulletin are recommended to be carried out by the operator and will be added to the Cameron Balloons Inspection Schedule at the next revision.

3. Materials

None

4. Other Publications Affected

None

5. Remarks

None

Compiled by: <i>[Signature]</i>		Notes:
Date: <i>16-1-20</i>	Name: <i>D. Boxer</i>	
6. Design Organisation Approval		
Approval Statement I hereby confirm that these instructions are in compliance with all the applicable airworthiness requirements. The technical content of this document is approved under the authority of DOA nr EASA.21J.140 Signed, for and on behalf of Cameron Balloons Ltd. <i>[Signature]</i>		
<i>PP</i> Head of Design		
Date: <i>17-01-2020</i>	Name:	